U.S. DEPARTMENT OF LABOR

Form No. LSB-00S-4
May 1969
DPM 392

UNIVIS PJ 42

WAGE AND LABOR STANDARDS ADMINISTRATION
Bureau of Labor Standards

MATERIAL SAFETY DATA SHEET

SEC	rion I
	on Corporation) Day 221-3424; Night 668-7024
ADDRESS (Number, Street, City, State, and ZIP Code) P.O. Box 2180 Houston, Texas 77001	622-1422
CHEMICAL NAME AND SYNONYMS Hydraulic Oil	TRADE NAME AND SYNONYMS UNIVIS PJ 42
CHEMICAL FAMILY Petroleum Hydrocarbon	FORMULA Complex mixture of petroleum hydrocarbons

SECTIO	II N	HAZAI	RDOUS INGREDIENTS		
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS		n.a.	BASE METAL		n.a.
CATALYST		n.a.	ALLOYS		n.a.
VEHICLE		n.a.	METALLIC COATINGS		n.a.
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX		n.a.
ADDITIVES			OTHERS		
OTHERS					
HAZARDOUS MIXTURE	SOFC	THER LIC	QUIDS, SOLIDS, OR GASES	%	TLY (Units)
This product is not	clas	sified	as a "Hazardous		
Material" in normal	use	as def	ined in U.S.		
Department of Labor	Regu	ılation	s 29 CFR Parts		
1501, 1502, and 1503	3.				

	SECTION III I	PHYSICAL DATA	
BOILING POINT (°F.) IBP	435	SPECIFIC GRAVITY (H20=1)	0.868
VAPOR PRESSURE (mm Hg.) @ 100°F	<1.0	PERCENT VOLATILE BY VOLUME (%)	Negligib
VAPOR DENSITY (AIR=1)	>6	evaporation rate (n-Butyl Acetate = 1)	<0.01
SOLUBILITY IN WATER	Negligibl		
APPEARANCE AND ODOR Clear red co	lor. Mild pe	troleum odor. /	

SECTION IV FIRE	E AND EXPLOSION HAZARD DATA		
FLASH POINT (Method used)	FLAMMABLE LIMITS	Lel	Uel
Cleveland Open Cup 210°F		1%	6%
EXTINGUISHING MEDIA Foam, dry chemical, CO ₂ , water spr	ay or fog.		
SPECIAL FIRE FIGHTING PROCEDURES			······································
Use air-supplied rescue equipment	for enclosed areas.		
Cool exposed containers with water	4		
UNUSUAL FIRE AND EXPLOSION HAZARDS			
Do not store or mix with strong ox	idants.		•

SECTION V HEALTH HAZARD DATA
THRESHOLD LIMIT VALUE 5 mg/m for oil mist.
effects of overexposure Prolonged or repeated skin contact may cause mild skin irritation.
EMERGENCY AND FIRST AID PROCEDURES If ingested do not induce vomiting, call a physician. Remove contaminated clothin
and wash skin with soap and water. In case of contact with eyes, flush eyes with
rector until invitation subsides

			SECT	ION VI RE	EACTIVITY DATA
STABILLTY	UNST	ABLE	·	CONDITION	S TO AVOID
	STAB	LE	X		
HAZARDOUS DE	<u>idants l</u> composition	.1Ke liqui N PRODUCTS			concentrated oxygen.
HAZARDOUS		MAY OCCUR			CONDITIONS TO AVOID
POLYMERIZATION	۷	WILL NOT OC	CUR	х	

TEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR	SPILLED	77 6-11-611	_
ecover free liquid. Add absorbe	nt to spill area.	Ventilate enclosed space	es.
Reep petroleum products out of st	reams and waterway	78.	
COP POULOUM PROGRAM OF ST			
	· · · · · · · · · · · · · · · · · · ·		
ASTE DISPOSAL METHOD			
ncinerate absorbed material.			
ASTE DISPOSAL MEJHOD ncinerate absorbed material.			

	SECTION VIII SPECIA	AL PROTECTION IN	VEORMATION	
RESPIRATORY PRO Normally no	TECTION (Specify type) of needed.			
VENTILATION LOCAL EXHAUST Face velocity > 60 fpm			SPECIAL	ing.
	MECHANICAL (General)		OTHER	
PROTECTIVE GLO Normally no		EYE PROTECTION		
	ve equipment Lous apron if needed.	Transport de consentation established in the consentation of the c		

			-				
			SECTION I	X SPECIAL P	ECAUTION		
RECAUTION Keep co	ns to be taken i ntainers c	n HANDLIN Losed.	g and storing Keep away	from heat	nd open	flame.	
other prec Avoid p	autions rolonged of	r repea	ted contact	t with skin	Remove	contaminated	clothing.
Jash sk	in with so	ap and y	water after	contact.			
Second date Secondary mines	Chief the Control of	taining to an administrative to the constitution of	managering to the control of the con	er beit a being eine er feltgeben der eine er bei der der eine der der der der der der der der der de	and his over lawer.		

James W. Hammond Director of Industrial Hygiene WISH-omask Wm. G. Domask, Ph.D., P.E. Government Regulations Advisor